



## Ultimate 150 Point Vehicle Inspection

Name: xxxxx

Year: 2014	Engine: 4.4L - V8
Make: BMW	Transmission: Auto
Model: M5	Exterior Color: White
Mileage: 58993	Interior Color: Black
VIN: 3749	Drive Type: RWD
Stock #:	Fuel Type: Gas

	EXTERIOR	OK	FAIR	POOR	N/A	NOTES
1	Body Panel Alignment	X				
2	Bumpers		X			Minor damage, scratches and paint chips on front
3	Dings and Dents	X				
4	Door Locks	X				
5	Doors	X				
6	Doors Seals	X				
7	Fenders	X				
8	Fuel Filler Cap	X				
9	Fuel Filler Door	X				
10	Grille	X				
11	Hazard Lights	X				
12	Headlights	X				
13	Hood	X				
14	Hood Hinges/Struts	X				
15	Hood Latch	X				
17	Key FOB	X				
18	Mirrors	X				
19	Paint Condition	X				
20	Paint Cracking	X				
21	Paint Oxidation	X				
22	Paint Scratches	X				
23	Quarter Panels	X				
24	Rear Window	X				
25	Rockers		X			Long, deep scratch on left rocker
26	Roof	X				
27	Rust	X				
28	Side Windows	X				

29	Tail Lights	X				
30	Trim	X				
31	Trunk/Bed/Cargo Area	X				
32	Turn Signals	X				
33	Windshield	X				A few very tiny rock/sand chips
34	Wiper Blades	X				

	PAINT/FILLER CHECK	OK	FAIR	POOR	N/A	Thickness in Mils
35	Left Fender	x				3 to 4
36	Left Doors	x				3 to 4
37	Left Quarter	x				4 to 6
38	Right Quarter	x				4 to 5
39	Right Doors	x				3 to 4
40	Right Fender	x				3 to 4
41	Hood	x				3 to 5
42	Roof	x				3 to 5
43	Trunk Lid	x				3 to 4

	TIRES & WHEELS	OK	FAIR	POOR	TREAD	NOTES
44	Left Front Tire	x			5/32	
45	Left Front Wheel	x				A few small scratches
46	Left Rear Tire	x			6/32	
47	Left Rear Wheel	x				
48	Right Rear Tire	x			6/32	
49	Right Rear Wheel	x				
50	Right Front Tire	x			5/32	
51	Right Front Wheel	x				
52	Spare Tire					No spare

	UNDERHOOD	OK	FAIR	POOR	N/A	NOTES
53	A/C Compressor	x				
54	Air Filter				x	
55	Alternator/Generator	x				
56	Battery	x				
57	Belts	x				
58	Brake Fluid Leaks	x				
59	Brake Master Cylinder	x				
60	Cooling Fan	x				
61	Emissions Equipment	x				
62	Engine Coolant	x				
63	Engine Noises	x				

64	Engine Oil Condition	x				
65	Engine Oil Leaks	x				
66	Hoses and Clamps	x				
67	Idler Pulleys	x				
68	Power Steering Fluid	x				
69	Power Steering Pump	x				
70	Radiator Cap	x				
71	Radiator Condition	x				
72	Transmission Fluid				x	
73	Windshield Washer	x				
74	Wiper Motor	x				

	<b>UNDERBODY</b>	<b>OK</b>	<b>FAIR</b>	<b>POOR</b>	<b>N/A</b>	<b>NOTES</b>
75	Axle Seals				x	
76	Ball Joints	x				
77	Brake System Leaks	x				
78	Coolant Leaks	x				
79	CV Joints & Boots	x				
80	Differential	x				
81	Drive Shaft & U-Joints	x				
82	Exhaust System	x				
83	Floor Pans - Rust	x				
84	Frame	x				
85	Fuel Tank	x				
86	Rust	x				
87	Signs of Damage	x				
88	Springs	x				
89	Steering Components	x				
90	Struts and Shocks	x				
91	Sway Bar Front	x				
92	Sway Bar Rear	x				
93	Transmission Leaks	x				
94	Transmission Mounts	x				

	<b>INTERIOR</b>	<b>OK</b>	<b>FAIR</b>	<b>POOR</b>	<b>N/A</b>	<b>NOTES</b>
95	A/C Temperature		x			Cool but not cold
96	Carpet Condition	x				
97	Clock	x				
98	Courtesy Lights	x				
99	Dash	x				
100	Dash Lights Working	x				

101	Defroster Front/Rear	x				
102	Door Locks	x				
103	Door Sill Plates	x				
104	Floor Mats	x				
105	Glove Box(s)	x				
106	Headliner/Sunroof	x				
107	Heater	x				
108	Hood Release	x				
109	Horn	x				
110	Inner Door Panels	x				
111	Instrument Gauges	x				
112	Interior Trim	x				
113	Map Lights	x				
114	Parking Brake	x				
115	Rear Camera	x				
116	Rear View Mirror	x				
117	Seat Adjustment	x				
118	Seat Belts	x				
119	Seat Condition	x				
120	Smoking Signs/Odors	x				
121	Sound System	x				
122	Steering Wheel	x				
123	Warning Lights	x				
124	Window Operation	x				
125	Window Tint	x				

	ROAD TEST	OK	FAIR	POOR	N/A	NOTES
126	AWD/4WD Operation	x				
127	Brakes/ABS Operation		x	x		Heavy wear on all 4 rotors - front have cracks - pulls left
128	Clutch Operation				x	
129	Cruise Control	x				
130	Differential Noises	x				
131	Engine Acceleration	x				
132	Engine Cruising	x				
133	Engine Idles Properly	x				
134	Engine Oil Pressure	x				
135	Engine Starts Easily	x				
136	Engine Temperature	x				
137	Gauges Operation	x				
138	Neutral Safety Switch	x				
139	Scan for OBD Codes	x				

140	Shift Interlock				x	
141	Smoke from Exhaust	x				
142	Squeaks and Rattles	x				
143	Starter Operation	x				
144	Steering Alignment	x				
145	Steering Response	x				
146	Struts and Shocks	x				
147	Tire Balance	x				
148	Transmission Shifting	x				Small lag from dual clutch engagement when stopped
149	Wind Noise	x				

150	Catalytic Converter			x		No catalytic converters
-----	---------------------	--	--	---	--	-------------------------

Summary: This is a normal mileage (58993) 2014 BMW M5 in overall good condition. On the exterior, the front bumper has some scratches, paint chips and some minor damage to the carbon fiber chin spoiler. There is also a long deep scratch on the left rocker and some very tiny rock/sand chips on the windshield. On the interior, the a/c blows cool but not cold and probably needs to be recharged. All 4 rotors show heavy wear with the front rotors having cracks where they were drilled. In addition, the catalytic converters have been removed to increase the horsepower and performance. On the road test, the engine ran well and the trans shifted normally. However, there is a small lag from when the dual clutch engages when stopped. The brakes also worked well during normal driving but pulled slightly to the left under heavy braking.

Inspected By: xxxxx

Date: xxxxx