



Premium 140-Point Vehicle Inspection

Name: xxxxx

Year: 2017	Engine: 5.3L - V8
Make: GMC	Transmission: Auto
Model: Yukon XL	Exterior Color: Dark Grey
Mileage: 41494	Interior Color: Black
VIN: 3401	Drive Type: 4WD
Stock #:	Fuel Type: Gas

	EXTERIOR	OK	FAIR	POOR	N/A	NOTES
1	Body Panel Alignment	X				
2	Bumpers		X	X		Rear repaint - front has scratches on bumper and air dam
3	Dings and Dents	X				
4	Door Locks	X				
5	Doors	X				
6	Doors Seals	X				
7	Fenders	X				
8	Fuel Filler Cap				X	
9	Fuel Filler Door	X				
10	Grille	X				
11	Hazard Lights	X				
12	Headlights	X				
13	Hood	X	X			Mark on center front of hood
14	Hood Hinges/Struts	X				
15	Hood Latch	X				
17	Key FOB	X				
18	Mirrors	X				
19	Paint Condition	X				
20	Paint Cracking	X				
21	Paint Oxidation	X				
22	Paint Scratches	X				
23	Quarter Panels	X				
24	Rear Window	X				
25	Running Boards	X				
26	Roof	X				
27	Rust	X				
28	Side Windows	X				
29	Tail Lights		X			Scratches on left tail light
30	Trim				X	
31	Trunk/Bed/Cargo Area		X			Scratches above left tail light and inside of cargo door
32	Turn Signals	X				

33	Windshield	x				
34	Wiper Blades	x				

	TIRES & WHEELS	OK	FAIR	POOR	TREAD	NOTES
35	Left Front Tire	x			7/32	
36	Left Front Wheel	x				
37	Left Rear Tire	x			7/32	
38	Left Rear Wheel	x				
39	Right Rear Tire		x		5/32	Excess wear on outside of tire
40	Right Rear Wheel		x			Scratches on 3 areas of wheel
41	Right Front Tire	x			7/32	
42	Right Front Wheel	x				
43	Spare Tire	x				

	UNDERHOOD	OK	FAIR	POOR	N/A	NOTES
44	A/C Compressor	x				
45	Air Filter				x	
46	Alternator/Generator	x				
47	Battery	x				
48	Belts	x				
49	Brake Fluid Leaks	x				
50	Brake Master Cylinder	x				
51	Cooling Fan	x				
52	Emissions Equipment	x				
53	Engine Coolant	x				
54	Engine Noises	x				
55	Engine Oil Condition	x				
56	Engine Oil Leaks	x				
57	Hoses and Clamps	x				
58	Idler Pulleys	x				
59	Power Steering Fluid	x				
60	Power Steering Pump	x				
61	Radiator Cap	x				
62	Radiator Condition	x				
63	Transmission Fluid	x				
64	Windshield Washer	x				
65	Wiper Motor	x				

	UNDERBODY	OK	FAIR	POOR	N/A	NOTES
66	Axle Seals	x				
67	Ball Joints	x				
68	Brake System Leaks	x				
69	Coolant Leaks	x				
70	CV Joints & Boots	x				
71	Differential	x				
72	Drive Shaft & U-Joints	x				
73	Exhaust System	x				Some surface rust

74	Floor Pans - Rust	x				
75	Frame	x				
76	Fuel Tank	x				
77	Rust	x				
78	Signs of Damage	x				
79	Springs	x				
80	Steering Components	x				
81	Struts and Shocks	x				
82	Sway Bar Front	x				
83	Sway Bar Rear	x				
84	Transmission Leaks	x				
85	Transmission Mounts	x				

	INTERIOR	OK	FAIR	POOR	N/A	NOTES
86	A/C Temperature	x				
87	Carpet Condition	x				
88	Clock	x				
89	Courtesy Lights	x				
90	Dash	x				
91	Dash Lights Working	x				
92	Defroster Front/Rear	x				
93	Door Locks	x				
94	Door Sill Plates	x				
95	Floor Mats				x	No floor mats
96	Glove Box(s)		x			No owner's manual
97	Headliner/Sunroof	x				A little dirty above cargo area
98	Heater	x				
99	Hood Release	x				
100	Horn	x				
101	Inner Door Panels	x				
102	Instrument Gauges	x				
103	Interior Trim	x				
104	Map Lights	x				
105	Parking Brake	x				
106	Rear Camera	x				
107	Rear View Mirror	x				
108	Seat Adjustment	x				
109	Seat Belts	x				
110	Seat Condition	x				
111	Smoking Signs/Odors	x				
112	Sound System	x				
113	Steering Wheel	x				
114	Warning Lights	x				
115	Window Operation	x				
116	Window Tint				x	

	ROAD TEST	OK	FAIR	POOR	N/A	NOTES
--	-----------	----	------	------	-----	-------

117	AWD/4WD Operation	x				
118	Brakes/ABS Operation	x				
119	Clutch Operation				x	
120	Cruise Control	x				
121	Differential Noises	x				
122	Engine Acceleration	x				
123	Engine Cruising	x				
124	Engine Idles Properly	x				
125	Engine Oil Pressure	x				
126	Engine Starts Easily	x				
127	Engine Temperature	x				
128	Gauges Operation	x				
129	Neutral Safety Switch	x				
130	Scan for OBD Codes	x				
131	Shift Interlock				x	
132	Smoke from Exhaust	x				
133	Squeaks and Rattles	x				
134	Starter Operation	x				
135	Steering Alignment	x				
136	Steering Response			x		Steering stops intermittently & dash lights go dim or off
137	Struts and Shocks	x				
138	Tire Balance	x				
139	Transmission Shifting	x				
140	Wind Noise	x				

Summary: This is a higher mileage (41494) 2017 GMC Yukon XL in overall good condition. On the exterior, the front bumper has a scratch in the middle and the air dam has deep scratches on both sides. The rear bumper has been repaired and repainted due to damage with the finish being a little cloudy. The left tail light has scratches on it and there are scratches above the left tail light and the hood has a 3-4" mark near the front. The right rear tire has excess wear on the outside edge and the wheel has scratches in 3 areas. On the interior, there are no floor mats and no owner's manual. On the road test, the steering wheel stops intermittently with the dash lights either going dim or completely going off. Suggest this be repaired asap as it is a safety issue and maybe be related to a steering gear, electrical issue or a factory recall. The engine did run well and the transfer case and the transmission worked properly. The brakes also worked well during normal driving and heavy braking.

Inspected By: xxxxx

Date: xxxxx