



Classic Vehicle Inspection

Name: xxxxx

Year: 1969	Engine: 350ci - V8
Make: Chevy	Transmission: Manual
Model: Corvette	Exterior Color: Red
Mileage: 19852	Interior Color: Black
VIN: xxxxx	Drive Type: RWD
Stock #:	Fuel Type: Gas

	EXTERIOR	OK	FAIR	POOR	N/A	NOTES
1	Body Panel Alignment	X				
2	Bumpers	X				
3	Dings and Dents	X				
4	Door Locks			X		No key for door locks
5	Doors		X			Large paint chip on left door - right door hard to open
6	Doors Seals			X		No door seals on either door
7	Fenders	X				
8	Fuel Filler Cap	X				
9	Fuel Filler Door	X				
10	Grille	X				
11	Hazard Lights	X				
12	Headlights		X			Right headlight not working
13	Hood	X				
14	Hood Hinges/Struts	X				
15	Hood Latch	X				
17	Key FOB				X	
18	Mirrors	X				
19	Paint Condition	X	X			Several small cracks
20	Paint Cracking	X				
21	Paint Oxidation	X				
22	Paint Scratches	X				
23	Quarter Panels	X				
24	Rear Window	X				
25	Rockers	X				
26	Roof				X	

27	Rust			x		Windshield pillars rusted on left and right side
28	Side Windows	x	x			Some scratches
29	Tail Lights	x				Small crack on right side
30	Trim				x	
31	Trunk/Bed/Cargo Area	x				
32	Turn Signals	x				
33	Windshield	x				
34	Wiper Blades	x				

	TIRES & WHEELS	OK	FAIR	POOR	TREAD	NOTES
44	Left Front Tire	x			9/32	
45	Left Front Wheel	x				
46	Left Rear Tire	x			8/32	
47	Left Rear Wheel	x				
48	Right Rear Tire	x			8/32	
49	Right Rear Wheel	x				
50	Right Front Tire	x			9/32	
51	Right Front Wheel	x				
52	Spare Tire			x		No spare

	UNDERHOOD	OK	FAIR	POOR	N/A	NOTES
53	A/C Compressor				x	
54	Air Filter	x				
55	Alternator/Generator	x				
56	Battery	x				
57	Belts	x				
58	Brake Fluid Leaks	x				
59	Brake Master Cylinder	x				
60	Cooling Fan	x				
61	Emissions Equipment				x	
62	Engine Coolant	x				
63	Engine Noises	x	x			Slight knock from center - possible valve noise
64	Engine Oil Condition	x				
65	Engine Oil Leaks	x				
66	Hoses and Clamps	x				
67	Idler Pulleys				x	
68	Power Steering Fluid	x				
69	Power Steering Pump	x				
70	Radiator Cap	x				
71	Radiator Condition	x				

72	Transmission Fluid				x	
73	Windshield Washer			x		Didn't work
74	Wiper Motor	x				

	UNDERBODY	OK	FAIR	POOR	N/A	NOTES
75	Axle Seals				x	
76	Ball Joints	x				
77	Brake System Leaks	x				
78	Coolant Leaks	x				
79	Axle Shaft U-Joints	x				
80	Differential	x				
81	Drive Shaft & U-Joints	x				
82	Exhaust System	x				
83	Floor Pans - Rust	x				
84	Frame	x				Some surface rust
85	Fuel Tank	x				New
86	Rust	x				
87	Signs of Damage	x				
88	Springs	x				
89	Steering Components	x				
90	Struts and Shocks	x				
91	Sway Bar Front	x	x			Torn bushings
92	Sway Bar Rear				x	
93	Transmission Leaks	x				
94	Transmission Mounts	x				

	INTERIOR	OK	FAIR	POOR	N/A	NOTES
95	A/C Temperature				x	
96	Carpet Condition	x				
97	Clock			x		Didn't work
98	Courtesy Lights			x		Didn't work
99	Dash		x			Small crack on left side
100	Dash Lights Working				x	Can't tell
101	Defroster Front/Rear	x				
102	Door Locks	x				
103	Door Sill Plates	x				
104	Floor Mats	x				
105	Glove Box(s)	x				
106	Headliner/Sunroof				x	
107	Heater			x		Didn't work

108	Hood Release	x				
109	Horn			x		Didn't work
110	Inner Door Panels	x				
111	Instrument Gauges		x			Gas gauge didn't work
112	Interior Trim	x				
113	Map Lights			x		
114	Parking Brake			x		Didn't work
115	Rear Camera				x	
116	Rear View Mirror	x				
117	Seat Adjustment	x				
118	Seat Belts	x				
119	Seat Condition	x				
120	Smoking Signs/Odors	x				
121	Sound System			x		Didn't work
122	Steering Wheel	x				
123	Warning Lights			x		Didn't work
124	Window Operation	x				
125	Window Tint				x	

	ROAD TEST	OK	FAIR	POOR	N/A	NOTES
126	AWD/4WD Operation				x	
127	Brakes/ABS Operation	x				Acceptable
128	Clutch Operation	x				
129	Cruise Control				x	
130	Differential Noises	x				
131	Engine Acceleration	x	x			
132	Engine Cruising	x				
133	Engine Idles Properly	x				
134	Engine Oil Pressure	x				
135	Engine Starts Easily	x				
136	Engine Temperature	x				
137	Gauges Operation		x			Gas gauge didn't work
138	Neutral Safety Switch	x				
139	Scan for OBD Codes				x	
140	Unusual Noises	x				
141	Smoke from Exhaust	x				
142	Squeaks and Rattles	x				
143	Starter Operation	x				
144	Steering Alignment	x				
145	Steering Response	x				

146	Struts and Shocks	x				
147	Tire Balance	x				
148	Transmission Shifting	x				
149	Wind Noise				x	
150	Convertible Top	x				

Summary: This is a driver's quality 1969 Chevy Corvette Convertible with 19852 miles on the odometer. On the exterior, there were several small cracks in the paint/fiberglass and a large repaired paint chip on the driver's door. There are no seals on either door, no key to lock/unlock the doors, a crack on the right taillight and the right headlight did not work. In addition, both windshield/A pillars are rusted through which may extend horizontally along the bottom of the windshield and down to the fender pillar. Under the hood, there is a slight knocking sound which seems to be from a valve and the windshield washer did not work. Under the body, there is some surface rust on the frame, the fuel tank is new and the bushing on the front sway bar is torn. On the interior, the clock, courtesy lights, heater, horn, gas gauge, parking brake and radio all did not work. On the road test, the engine ran good and the transmission and clutch operated properly. The brakes were acceptable during normal driving.

Inspected By: xxxxx

Date: xxxxx
